

Goodyear Electronics, Inc

OS-303/54831M Repair Pricing

Currently, established repair prices are available for the Acquisition card and the PC Motherboard only.

Acquisition Board Repair: \$1500

PC Motherboard Repair: \$1200

We are in the process of acquiring exchange stock for the 54831M, but selection and quantity are very limited at this time. If you are looking for a subassembly other than the two listed above, contact us for pricing and availability.